

● PRINTER RUSH ●
(PTO ASSISTANCE)

Application : <u>10/757162</u>	Examiner : <u>Banks</u>	GAU : <u>3725</u>
From : <u>PAP</u>	Location : <u>IDC</u> FMF FDC	Date : <u>5/12/05</u>
Tracking # : <u>06086938</u>		Week Date : <u>3/14/05</u>

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449	_____	<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS	_____	<input type="checkbox"/> Foreign Priority
<input type="checkbox"/> CLM	_____	<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW	_____	<input type="checkbox"/> Fees
<input type="checkbox"/> SRFW	_____	<input type="checkbox"/> Other
<input checked="" type="checkbox"/> DRW	<u>1/14/2004</u>	
<input type="checkbox"/> OATH	_____	
<input type="checkbox"/> 312	_____	
<input type="checkbox"/> SPEC	_____	

[RUSH] MESSAGE: Attention Chief Draftsperson: Please provide a new drawing sheet for Figure 34 - a lead line is missing a reference number.

82

Thank you

[XRUSH] RESPONSE: _____

RESOLVED CORRECTED DRAWINGS
5-24-2005 ATTACHED

INITIALS: [Signature]

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.
REV 10/04

27/30




Figure - 34